

# Handi-Ramp®

Since 1958

(800) 876-RAMP

## CASE STUDY

Challenge

Solution

Outcome

### CHALLENGE:

Debbie Johson discovered an unwelcome visitor in her basement one February morning. A deer had fallen through her existing window well cover and gotten into her basement. The window well cover made of plastic was not strong enough to sustain the weight of the large animal. The cover did not properly fit her window well and created less security and protection from leaves, debris and animals.

### SOLUTION:

Handi-Ramp custom manufactured a window well cover constructed from expanded steel. This added strength would withstand the rigors of both weather and heavy objects. The window well cover offered long-term safety and protection from unwanted visitors, while providing an exit in case of an emergency.

### OUTCOME:

- The window well is secure from external access and prevents unwanted visitors into the house.
- The cover fit snugly over the window well since it was custom manufactured to fit.

### WINDOW WELL COVERS



Handi-Ramp®

Since 1958

(800) 876-RAMP

510 North Avenue  
Libertyville, IL 60048  
847-816-8866 (fax)  
www.handiramp.com

#### Learn more from our Handi-Ramp Project Specialists:

Greg Hogarty (847) 247-2359 - ghogarty@handiramp.com  
Al TerBush (847) 996-6290 - aterbush@handiramp.com  
Chris Diver (847) 247-2358 - cdiver@handiramp.com  
Mike Myers (847) 996-6848 - mmyers@handiramp.com  
Joseph Russell (847) 247-2351 - jrussell@handiramp.com

*Handi-Ramp was very concerned about providing a professional & affordable solution. I am so impressed by the excellent overall quality of the window well cover.*

~ Debbie Johnson